

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/21/2019

Submitted Date:

05/24/2019

Document Number:

692401004**FIELD INSPECTION FORM**

Loc ID 419862	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____
------------------	-------------------------------	---	-------------------

Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:

☒ THIS IS A FOLLOW UP INSPECTION

☒ FOLLOW UP INSPECTION REQUIRED

☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
419865	WELL	PR	02/01/2015	GW	045-20039	Mead RWF 32-23	RI
419866	WELL	PR	06/30/2015	OW	045-20040	Mead RWF 342-23	RI
419867	WELL	PR	02/01/2015	GW	045-20041	Mead RWF 633-23	RI
419870	WELL	PR	02/01/2015	OW	045-20044	Mead RWF 432-23	RI
419872	WELL	PR	06/30/2015	OW	045-20046	Mead RWF 341-23	RI
419873	WELL	PR	02/01/2015	GW	045-20047	Mead RWF 431-23	RI
419876	WELL	PR	06/30/2015	OW	045-20050	Mead RWF 43-23	RI
419877	WELL	PR	07/03/2015	OW	045-20051	Mead RWF 531-23	RI
419878	WELL	PR	02/01/2015	GW	045-20052	Mead RWF 332-23	RI
419879	WELL	PR	08/01/2015	SI	045-20053	Mead RWF 331-23	RI

General Comment:

[This is an Interim Reclamation & Stormwater focused Inspection; a Follow Up to Insp Doc#674104548 Dated 7/7/18. Any Corrective Actions from previous Inspections that have not been addressed are still applicable.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

DEBRIS

Comment:

Dead Annual Weeds that have broken off and become Debris have blown behind Equipment & in depressions in several areas of site.

Corrective Action:

Comply with Rule 603.f .

Date: 06/07/2019

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities				
Facility ID: <u>419865</u>	Type: <u>WELL</u>	API Number: <u>045-20039</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>419866</u>	Type: <u>WELL</u>	API Number: <u>045-20040</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>419867</u>	Type: <u>WELL</u>	API Number: <u>045-20041</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>419870</u>	Type: <u>WELL</u>	API Number: <u>045-20044</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>419872</u>	Type: <u>WELL</u>	API Number: <u>045-20046</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>419873</u>	Type: <u>WELL</u>	API Number: <u>045-20047</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>419876</u>	Type: <u>WELL</u>	API Number: <u>045-20050</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>419877</u>	Type: <u>WELL</u>	API Number: <u>045-20051</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>419878</u>	Type: <u>WELL</u>	API Number: <u>045-20052</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>419879</u>	Type: <u>WELL</u>	API Number: <u>045-20053</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment

Since the Previous R Inspection: old BMP straw bales & staking piled at Southwest side of site that had become Debris have been removed; the heavy senesced Annual Weed Growth in Interim Reclamation was not evident.

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? <u>Pass</u>	Production areas stabilized ? <u>Pass</u>
1003c. Compacted areas have been cross ripped? _____	
1003d. Drilling pit closed? <u>Pass</u>	Subsidence over on drill pit? <u>Pass</u>
Cuttings management: _____	
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? <u>In</u>	
Production areas have been stabilized? <u>Pass</u>	Segregated soils have been replaced? _____
RESTORATION AND REVEGETATION	
<u>Cropland</u>	
Top soil replaced _____	Recontoured <u>Fail</u> Perennial forage re-established <u>In</u>
<u>Non-Cropland</u>	
Top soil replaced _____	Recontoured <u>Pass</u> 80% Revegetation _____
1003e. INTERIM VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% _____	
TRANSECT RESULTS OF REFERENCE AREA% _____	
TOTAL % OF DESIRABLE VEGETATION COVER _____	
VEGETATIVE COVER _____	
1003 f. Weeds Noxious weeds? <u>P</u>	
Comment	<div style="border: 1px solid black; padding: 5px;"> <p>Majority of the interim reclamation areas appear to be an almost monoculture of Cheat grass, though some cool season grasses were emerged.</p> <p>Interim Rec @ South end of site where sound barrier was, has been worked & newly seeded. It appears this site, which is to be reclaimed as irrigated hayfield, still, has not had enough soil added to bring it up to grade with contiguous field or if top soil was found for top layer. There is also concern of what seed mix was used. Erosion is occurring in new seedbed. If this area is reinstalled, Operator is encouraged to consult with Surface Owner as to seed mix, inputs needed, timing of activities, allowing SO to incorporate into irrigation system.</p> </div>
Corrective Action	<div style="border: 1px solid black; padding: 5px;"> <p>CA#1) Provide Seed Mixes used on both areas of Reclamation by 6/7/19.</p> <p>CA#2) Conduct Vegetation assessment in non-crop areas of Reclamation by 6/30/19. Monitor crop area of Interim. In both areas --re-seeding/ inter-seeding, amending soil; adding topsoil if/as determined necessary by assessment.</p> </div>
Overall Interim Reclamation <u>In Process</u>	
<u>Final Reclamation/ Abandoned Location:</u>	
Date Final Reclamation Started: _____	Date Final Reclamation Completed: _____
Final Land Use: <u>RANGELAND</u>	
Reminder: _____	
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>	
Well plugged _____	Pit mouse/rat holes, cellars backfilled _____
Debris removed _____	No disturbance /Location never built _____
Access Roads Regraded _____	Contoured _____ Culverts removed _____
Gravel removed _____	
Location and associated production facilities reclaimed _____	Locations, facilities, roads, recontoured _____
Compaction alleviation _____	Dust and erosion control _____
Non cropland: Revegetated 80% _____	Cropland: perennial forage _____
Weeds present _____	Subsidence _____
1004.d. FINAL VEGETATION TRANSECT	

TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Erosion is occurring in new seed bed of Hayfield Interim, on Cut slopes, and in big rock drain that flows to lage sediment trap at West edge of site. Sediment is migrating onto & off of site. Refer to Photo Log attached.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 06/25/2019

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402055145	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4832040
692401012	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4832033