

Inspection Photos  
Location Name: BLACK BUCK 21-6  
API #: 05-071-08864  
INSP. #:695100768



**PHOTO 1: WELLHEAD**



**PHOTO 2: CURRENT OPERATOR NOT POSTED ON WELL SIGN.  
CHANGE OPERATOR NAME TO CURRENT OPERATOR IN  
ACCORDANCE WITH RULE 210. CA DATE 7/30/19**

## Inspection Photos

Location Name: BLACK BUCK 21-6

API #: 05-071-08864

INSP. #:695100768



**PHOTO 3: DRAINAGE DITCH ON ROW JUST WEST OF LOCATION ROW ENTRANCE HAS NO BMP'S OR BMP'S OR INADEQUATE. REPAIR OR INSTALL BMP'S TO PREVENT EROSION IN ACCORDANCE WITH 1002 SERIES RULES. CA DATE 6/30/19.**