

**Inspection Photos**  
**Operator: Catamount Energy**  
**Location/API #: 067-07933**  
**Date: 5-23-2319**



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of an erosional channel forming within the southeastern project area.



Photo 3. View of what appears to be active head-cut erosion down-slope from the eastern edge of the project area where concentrated stormwater flows off of the well pad.