

Inspection Photos  
Location Name: William D Lansdown #1  
Location ID: 317613



**Pic 1 no cap on casing valve sign faded**



**Pic 2 unused tubulars on location**

Inspection Photos  
Location Name: William D Lansdown #1  
Location ID: 317613



**Pic 3 separator house in poor condition**



**Pic 4**

Inspection Photos  
Location Name: William D Lansdown #1  
Location ID: 317613



Pic 5



Pic 6 uncapped unmarked risers

Inspection Photos  
Location Name: William D Lansdown #1  
Location ID: 317613



**Pic 7 inadequate berms around water tank**



**Pic 8 unused unmarked uncapped risers on location/stained soil**

Inspection Photos  
Location Name: William D Lansdown #1  
Location ID: 317613



**Pic 9 inadequate berms around oil tank, placards and sign is not legible**