

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Lease road entrance		
Corrective Action:		Date:	
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

--

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 283679 Type: WELL API Number: 123-23664 Status: PR Insp. Status: WK

BradenHead

Comment: IBH @ 0.3 psig with water flow

Corrective Action:

Date:

Workover

Comment: Drill out cement inside of surface casing from 168' KB to 292' KB, circulate clean, POOH to 262' KB, SIW, SDFN.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696500007	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4837627