

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/15/2019

Submitted Date:

05/16/2019

Document Number:

689900685

FIELD INSPECTION FORM

Loc ID 324823 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 83130

Name of Operator: STRACHAN EXPLORATION INC

Address: 383 INVERNESS PKWY, STE 360

City: ENGLEWOOD State: CO Zip: 80112

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Strachan, Steve	(303) 785-7006	sms@strachanexploration.com	
Kosola, Jason		jason.kosola@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212935	WELL	PR	07/01/2017	GW	061-06296	FRAZEE 1-6	RI

General Comment:

Location and Stormwater inspection.

Location				
Lease Road:				
Type	Access			
comment:	See stormwater section. Corrective action required.			
Corrective ActionL				Date:
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date:
Corrective Action:				
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	There is a unused tank trailer on location.			
Corrective Action:	Comply with Rule 603.f .			Date: 06/15/2019
Type	DEBRIS			
Comment:	There is role of barbed wire on the H brace.			
Corrective Action:	Comply with Rule 603.f .			Date: 06/15/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
Crude Oil	Pump Jack			
Comment:	907.e. Oily Waste. There is oil stained soil at the well head. There is also staining at the tank outlet and hose. No secondary containment. See Photos			
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.. Contact area COGCC EPS			Date: 05/20/2019
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type				
Comment:	The fence around the equipment are insufficient to prevent livestock entry.			
Corrective Action:	Comply with the fencing requirements per the 1002a rules			Date: 06/15/2019
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: The access road is not maintained and does not adequately drain stormwater. As a result, vehicles are traveling outside of the access road creating significant disturbance and soil compaction. See Attached Photos

Corrective Action: Prevent vehicle disturbance outside of the access road and reclaim disturbance. Properly grade and install road base to allow stormwater draiange. Install or repair required BMPs per Rule 1002.f.

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402046847	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4825400
689900686	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4825399