

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/31/2019

Submitted Date:

06/01/2019

Document Number:

696100970

FIELD INSPECTION FORMLoc ID 328688 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248508	WELL	TA	06/01/2018	OW	123-16306	SINJIN E 36-13	TA

General Comment:

This is a WELL & BATTERY inspection.
 Well: Shut-In (SI).
 Entire battery & equipment is shut-down.
 Centralized Battery serves 6 Location IDs (328688, 302782, 305188, 323346, 328685, 328687).
 (6 - wells ; Temporarily Abandoned - TA).
 Centralized Battery formerly served 1 Location ID (328686).
 (1 - well ; Plugged & Abandoned - PA)
 Follow-up to Field Inspection Report Doc. #691201083 dated 01/18/2019

Location**Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Prior & current insp: SI/TA well per Alternative Mechanical Integrity Assurance Program. Doc #02385001 (NOBLE) . Decommission / LTSI tags for SI/TA status NOT present at wellsite. Master valve / Casing valve NOT LOTO. Install Decommission / LTSI tags for SI/TA status / LOTO to comply with Doc #02385001. Original Corrective Action Date: Open Original Corrective Action Date remains applicable. See photo #1.		
Corrective Action:	Install Decommission / LTSI tags for SI/TA status / LOTO to comply with Doc #02385001. Original Corrective Action Date: Open Original Corrective Action Date remains applicable.	Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment (well fittings & piping) at wellsite. Refer to Rule 603.f. Remove unused equipment (well fittings & piping) at wellsite. Comply w/ Rule 603.f. See photo #1.		
Corrective Action:	Remove unused equipment (well fittings & piping) at wellsite. Comply w/ Rule 603.f. See photo #1.	Date:	07/03/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	ECD scrubbers.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	WELLHEAD: w/ Master & casing valves.		
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:	ECD #1: Controls crude oil tanks VOCs. ECD #2: Controls separator VOCs. Pilots: OFF Shut-down.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 6 Location IDs (328688, 302782, 305188, 323346, 328685, 328687). Centralized Battery formerly served 1 Location ID (328686). (1 - well ; Plugged & Abandoned - PA)				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:
<u>Paint</u>					
Condition					
Other (Content)					
Other (Capacity)	60 Bbls.				
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	Shares berms w/ crude oil tanks & 48 Bbls. produced H2O vaults.				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:
<u>Paint</u>					
Condition					
Other (Content)					
Other (Capacity)	48 Bbls.				
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	Shares berms w/ crude oil tanks & 60 Bbls. produced H2O vault.				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLS	STEEL AST		40.435390,-104.611740
Comment:	Equalizer line connects West & Middle crude oil tanks.				
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					

Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares berms w/ produced H2O vaults.					
Corrective Action:				Date:	
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	248508	Type:	WELL	API Number:	123-16306	Status:	TA	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned Reminder: _____									
<div>Comment: <div>Temporarily Abandoned (TA). Wellhead disconnected from flowline. COGCC records indicate last prod: 01/2017. SI/TA well per Alternative Mechanical Integrity Assurance Program. Doc #02385001 (NOBLE) .</div></div>									
Corrective Action: _____ Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 05/31/2019 at approximately 12:56 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: SINJIN-66N65W /36SWSW Location ID: 328688 Location County: Weld County, Colorado Weather: Wet w/ mud & puddles from prior rain.</p> <p>While there, I observed: Well(s) - 1: Shut-In (SI). Entire battery & equipment is shut-down. Centralized Battery serves 6 Location IDs (328688, 302782, 305188, 323346, 328685, 328687). Centralized Battery formerly served 1 Location ID (328686). (1 - well ; Plugged & Abandoned - PA) Follow-up to Field Inspection Report Doc. #691201083 dated 01/18/2019 1 of 1: Corrective Actions appears NOT addressed. 1.) SI/TA well per Alternative Mechanical Integrity Assurance Program. Doc #02385001 (NOBLE) . Decommission / LTSI tags for SI/TA status NOT present at wellsite. Master valve / Casing valve NOT LOTO. Install Decommission / LTSI tags for SI/TA status / LOTO to comply with Doc #02385001. Original Corrective Action Date: Open See photo #1.</p> <p>1: NEW Corrective Actions observed. 1.) Unused equipment (well fittings & piping) at wellsite. Refer to Rule 603.f. Remove unused equipment (well fittings & piping) at wellsite. Comply w/ Rule 603.f. Corrective Action Date: 07/03/2019. See photo #1.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	05/31/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100971	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4837775