

Inspection Photos

API: 05-071-06340

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 6/3/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06340 | Date: 6/3/2019

Inspection Photos



Photo 1. Facing northwest at mouth of the canyon. It appears stormwater has flowed across the road at this point causing damage.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06340 | Date: 6/3/2019

Inspection Photos



Photo 2. Facing back to the southeast. Erosion is occurring along the side of the road and no BMPs are installed (checkdamns).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06340 | Date: 6/3/2019

Inspection Photos



Photo 3. Stormwater is pooling onto the road and is not properly diverted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06340 | Date: 6/3/2019

Inspection Photos



Photo 4. The erosion channel at the southeast side of the location has not been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06340 | Date: 6/3/2019

Inspection Photos



Photo 5. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06340 | Date: 6/3/2019