

Inspection Photos

API: 05-071-08419

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 6/3/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08419 | Date: 6/3/2019

Inspection Photos



Photo 1. Facing west along the main road near the gate of Cherry canyon. Erosion issues have been repaired in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08419 | Date: 6/3/2019

Inspection Photos



Photo 2. Facing northwest along the main road at the gate of Cherry canyon. Erosion issues have been repaired in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08419 | Date: 6/3/2019

Inspection Photos



Photo 3. The culvert has been cleaned out and repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08419 | Date: 6/3/2019

Inspection Photos



Photo 4. Culvert up the road has been cleaned out. Water shown in the photo is not draining well thru the culvert. This may create issues in the future.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08419 | Date: 6/3/2019

Inspection Photos



Photo 5. Culvert was repaired however, sediment is already filling up the culvert. Check dams may need to be installed up the road further.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08419 | Date: 6/3/2019

Inspection Photos



Photo 6. Additional rip/rap has been added to the outlet of the culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08419 | Date: 6/3/2019

Inspection Photos



Photo 7. There is still erosion issues at the east side of the pad.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08419 | Date: 6/3/2019

Inspection Photos



Photo 8. The door on the trash container was open.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08419 | Date: 6/3/2019

Inspection Photos



Photo 9. Berm was added around soil pile.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08419 | Date: 6/3/2019

Inspection Photos



Photo 10. Rip/rap was added to control erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08419 | Date: 6/3/2019