

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/03/2019

Submitted Date:

06/03/2019

Document Number:

696100988**FIELD INSPECTION FORM**
 Loc ID 333034 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name   | Phone | Email                              | Comment                         |
|----------------|-------|------------------------------------|---------------------------------|
| Pesicka, Conor |       | conor.pesicka@state.co.us          |                                 |
| ,              |       | NBL_DJBU_Inspections@nblenergy.com | <a href="#">All Inspections</a> |
| ,              |       | dnr_cogccengineering@state.co.us   |                                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 288969      | WELL | SI     | 02/01/2016  | OW         | 123-24711 | COCKROFT USX A 11-8 | TA          |

**General Comment:**

This is a WELL & ABANDONED BATTERY Inspection.  
 Well: Temporarily Abandoned (TA).  
 Battery: Abandoned & ALL equipment removed.  
 Abandoned Battery SE corner GPS coordinates: 40.499600, -104.509520  
 Reclamation progressing.  
 Follow-up to Field Inspection Report Doc. #684904895 dated 01/19/2018.

| Location   |  |        |                  |
|--|--|--------|------------------|
| <b>Lease Road:</b>                                     |  |        |                  |
| Type   | Access   |        |                  |
| comment:   | Adequate   |        |                  |
| Corrective Action                                      | L  |        | Date:            |
| Overall Good: <input type="checkbox"/>                 |  |        |                  |
| <b>Signs/Marker:</b>                                   |  |        |                  |
| Type   | WELLHEAD   |        |                  |
| Comment:   |  |        |                  |
| Corrective Action:                                     |  |        | Date:            |
| Emergency Contact Number:                              |  |        |                  |
| Comment:   |  |        |                  |
| Corrective Action:                                     |  |        | Date: _____      |
| <b>Good Housekeeping:</b>                              |  |        |                  |
| Type   | WEEDS  |        |                  |
| Comment:   | Prior insp:<br>Weed encroachment in berms, in tank battery. Refer to Rule 603.f.<br>Remove, manage, & control weeds around Battery site. Comply with Rule 603.f.<br>Original Corrective Action date: 01/29/2019.<br>This insp:<br>* Battery Abandoned. ALL equipment removed. Weeds appear mitigated.<br>See photos #3, 4. |        |                  |
| Corrective Action:                                     |  |        | Date:            |
| Type   | UNUSED EQUIPMENT   |        |                  |
| Comment:   | Unused equipment (automation equipment on ground) at wellsite. Refer to Rule 603.f.  |        |                  |
| Corrective Action:                                     | Remove unused equipment (automation equipment on ground) at wellsite. Comply w/ Rule 603.f. See photo #2.  |        | Date: 07/03/2019 |
| Overall Good: <input type="checkbox"/>                 |  |        |                  |
| <b>Spills:</b>   |  |        |                  |
| Type   | Area   | Volume |                  |
| In Containment: No                                     |  |        |                  |
| Comment: _____   |  |        |                  |
| <input type="checkbox"/> Multiple Spills and Releases? |  |        |                  |
| <b>Fencing/:</b>                                       |  |        |                  |
| Type   | WELLHEAD   |        |                  |
| Comment:   | Iron panel   |        |                  |
| Corrective Action:                                     |  |        | Date:            |
| <b>Equipment:</b>                                      |  |        |                  |
| Type: Bradenhead                                       | # 1  |        | corrective date  |
| Comment:   | Appears plumbed to surface.  |        |                  |

|                    |     |       |  |
|--------------------|-----|-------|--|
| Corrective Action: |     | Date: |  |
| Type: Plunger Lift | # 1 |       |  |
| Comment:           |     |       |  |
| Corrective Action: |     | Date: |  |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 288969 Type: WELL API Number: 123-24711 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Prior insp:  
SI. Last produced Dec 2015. No current MIT on record or delinquent as required by Rule 326.  
Contact dnr\_cogccengineering@state.co.us with resolution plan.  
Original Corrective Action date: 01/29/2019.  
This insp:  
\* Temporarily Abandoned (TA). Battery Abandoned.  
COGCC records indicate last prod: 01/2016.  
SI/TA well per Alternative Mechanical Integrity Assurance Program. Doc #02385001 (NOBLE) .

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           |                 | Gravel                  |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <p><b>COGCC Inspection Report Summary:</b></p> <p>On MON JUN 03, 2019 at approximately 13:33 hrs. I, Bret Evins, conducted an on-site inspection at:<br/> Operator Name: NOBLE ENERGY INC<br/> Location Name: COCKROFT USX A-66N64W /11SENE<br/> Location ID: 333034<br/> Location County: Weld County, Colorado<br/> Weather: Cloudy / Dry.<br/> While there, I observed: 1-Well(s) Temporarily Abandoned (TA).<br/> Battery: Abandoned &amp; ALL equipment removed.<br/> Abandoned Battery SE corner GPS coordinates: 40.499600, -104.509520<br/> Reclamation progressing.</p> <p>Follow-up to Field Inspection Report Doc. #684904895 dated 01/19/2018.<br/> 2: Corrective Actions appear addressed.<br/> 1.) Weed encroachment in berms, in tank battery.<br/> Refer to Rule 603.f.<br/> Remove, manage, &amp; control weeds around Battery site. Comply with Rule 603.f.<br/> Original Corrective Action date: 01/29/2019.<br/> * Battery Abandoned. ALL equipment removed. Weeds appear mitigated.<br/> See photos #3, 4.<br/> 2.) SI. Last produced Dec 2015. No current MIT on record or delinquent as required by Rule 326.<br/> Contact <a href="mailto:dnr_cogccengineering@state.co.us">dnr_cogccengineering@state.co.us</a> with resolution plan.<br/> Original Corrective Action date: 01/29/2019.<br/> * Temporarily Abandoned (TA). Wellhead disconnected from flowline.<br/> COGCC records indicate last prod: 01/2016.<br/> SI/TA well per Alternative Mechanical Integrity Assurance Program. Doc #02385001 (NOBLE) .</p> <p>1: NEW Corrective Actions observed.<br/> 1.) Unused equipment (automation equipment on ground) at wellsite. Refer to Rule 603.f.<br/> Remove unused equipment (automation equipment on ground) at wellsite. Comply w/ Rule 603.f.<br/> See photo #2.<br/> Corrective Action date: 07/3/2019.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p> | evinsb | 06/03/2019 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 696100989    | Site photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4838823">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4838823</a> |

