

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/28/2019

Submitted Date:

05/28/2019

Document Number:

687904826**FIELD INSPECTION FORM**
 Loc ID 326263 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**17 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216135	WELL	PR	09/26/2007	GW	067-07741	ANNALA FEDERAL A 1	PR

**General Comment:**[Site inspection with photos at the end of this report.](#)

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign posted at entrance to location.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank labels and placards posted.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Contact information posted.

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	Plumbed to surface.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Engine oil day tank has stained soil/gravel around spill prevention. See photo #5		
Corrective Action:	Remove and dispose of contaminated soil/gravel per Rule 1002.f.(2)	Date:	06/28/2019
Type: Flow Line	# 6		
Comment:	1-3" flowline from wellhead to separator. 1-1" flowline from wellhead to pumpjack engine fuel gas supply. 1-2" flowline from separator to produced water tank. 1-2" flowline from separator dump valve to offsite produced water gathering system. 1-3" flowline from separator to meter house. 1-3" flowline from meter house to offsite dogleg.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Natural gas engine has exhaust leak. Visible spotting of stained soil/gravel below exhaust piping. See photo #3		
Corrective Action:	Clean up and dispose of affected area per Rule 1002.f.(2).	Date:	06/28/2019
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Stained soil/gravel around wellhead. See photo #2		
Corrective Action:	Clean-up and dispose per Rules 907.e. and 1002.f.(2).	Date:	06/28/2019

Type: Bird Protectors	# 1		
Comment:	On separator stack.		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Gearbox drain plug with visible oil down side of pumpjack. See photo#6		
Corrective Action:	Securely fasten to ensure good mechanical condition per Rule 605.d.		Date: 06/28/2019

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	216135	Type:	WELL	API Number:	067-07741	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing.								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
				Material Handling And Spill Prevention	Pass	Spill prevention for engine oil day tank.
Gravel	Pass					
Waddles	Fail	Compaction	Pass			See Comment below fo BMP's

Comment: -Several waddles along southern edge of location not maintained or deteriorated causing erosion and channeling of silt offsite. See photo #7,8,9,10,11,12,13

Corrective Action: Maintain, install or replace all in-place requird BMP's per Rule 1002.f.(2)

Date: 06/28/2019

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402057137	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4833688">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4833688</a>
687904827	ANNALA FEDERAL A1 inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4833651">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4833651</a>