

Location

Overall Good:

Signs/Marker:

	Type OTHER		
Comment:	frac: Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:		Date:	

Flaring:

Type			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 457271 Type: WELL API Number: 123-47866 Status: DG Insp. Status: DG

Well Stimulation

Stimulation Company: Liberty oilfield services Stimulation Type: HYDRAULIC FRAC

Observation:

Other: _____

Maximum Casing Recorded: 7863 PSI

Tubing: _____

Surface: _____

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) _____

Bradenhead Psi: 0

Frac Flow Back: Fluid: _____ Gas: _____

Comment: _____

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass	Covering Materials	Pass	
Ditches	Pass	Ditches	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine inspection. Frac crew is on the last three wells of the location. Weather conditions: Clear and sunny road and loction are dry	silverr	06/04/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693500280	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4839982