

Inspection Photos
Loc#335019
Operator: Caerus
Insp#692401029
Inspection Date: 5/22/2019






Photo#1:
Overview of Location to Northwest.

May 22, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Schideler Loc#335019



Photo#2:
Views of Ponding at Wellhead area

May 22, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Schideler Loc#335019



Photo#3:
View East to West over Wellhead lineup.

May 22, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Schideler Loc#335019



Photo#4:
Run-on is occurring at access road entry

May 22, 2019



Photo#5:
Run-on is occurring at access road entry.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Schideler Loc#335019