

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/29/2019

Submitted Date:

05/29/2019

Document Number:

679600845

FIELD INSPECTION FORM

Loc ID 428210 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

Findings:

- 14 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
,		cogccinspection@pdce.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428199	WELL	PR	02/28/2013	OW	123-35275	Magnuson 23I-221	PR
428207	WELL	PR	04/11/2019	OW	123-35278	Magnuson 23L-201	PR
429399	WELL	PR	04/01/2013	OW	123-35801	Magnuson 23L-421	PR
429641	WELL	PR	05/05/2013	OW	123-35854	Magnuson 23I-421	PR

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate (x4)		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			Date: _____
Corrective Action:			

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Tubing in second separator, valve in fencing with wellhead. See attached photos.		
Corrective Action:	Comply with Rule 603.f.	Date:	06/08/2019
Type	TRASH		
Comment:	Trash in north seperator and in gas meter house. See attached photos.		
Corrective Action:	Comply with Rule 603.f.	Date:	06/08/2019

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	WELLHEAD		
Comment:	Panel (x4)		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 3		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 6		
Comment:	Methanol pumps in self containment.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	100 BBLs	PBV FIBERGLASS		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with crude oil tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	12	400 BBLs	STEEL AST		40.554100,-104.752300
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:				
----------	--	--	--	--

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
--------	----	--	--

Comment:			
----------	--	--	--

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
------	--	--	--

Comment:			
----------	--	--	--

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	<u>428199</u>	Type:	<u>WELL</u>	API Number:	<u>123-35275</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>PR</u>								
Corrective Action:								Date:	
Facility ID:	<u>428207</u>	Type:	<u>WELL</u>	API Number:	<u>123-35278</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>PR</u>								
Corrective Action:								Date:	
Facility ID:	<u>429399</u>	Type:	<u>WELL</u>	API Number:	<u>123-35801</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>PR</u>								
Corrective Action:								Date:	
Facility ID:	<u>429641</u>	Type:	<u>WELL</u>	API Number:	<u>123-35854</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>PR</u>								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Comment: <input style="width: 90%;" type="text"/> Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday, May 29, 2019 at approximately 15:15, I, Inspector Brittani Santistevan, conducted an on-site inspection at MAGNUSON 23I-221, 23L-421, 23L-201, 23I-421 (PDC Energy), at location #: 428210 in WELD COUNTY Colorado. While there, I observed producing wells. During this inspection the following possible compliance issues were observed: 1. Unused equipment in second separator house, valve in wellhead fencing . COMPLY WITH RULE 603.F. (Corrective Action Date: June 8, 2019) See attached photo #2 in Magnuson 23I-421 photos and photo #4 in location photos. 2. Trash in gas meter house and in north separator. COMPLY WITH RULE 603.F. (Corrective Action Date: June 8, 2019). See attached photo #2 and #6 in location photos. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> <p>Continuing Education Inspection.</p>	santistb	05/29/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402058539	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4834801
679600846	Magnuson 23I-421 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4834775
679600847	Wellhead Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4834776
679600848	Wellhead Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4834777
679600849	Wellhead Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4834778
679600850	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4834779