

## Inspection Photos

Location Name: STATE OF COLORADO AS 42-36V

API#: 05-071-07274

INSP. #: 695100789



**PHOTO 1: ORIGINAL WELLHEAD**

**PHOTO 2: V WELLHEAD**

## Inspection Photos

Location Name: STATE OF COLORADO AS 42-36V FOLLOWUP

API#: 05-071-07274

INSP. #: 695100789



**PHOTO 3: WELL SIGNS/ CURRENT OPERATOR IS NOT POST ON WELL SIGN. COMPLY WITH 210 SERIES RULES. CA DATE 7/4/19.**

**PHOTO 4: TRASH SHOWN IN PHOTO 3: OF INSP. DOC# 691401803 ORIGINAL CA DATE 2/8/19 HAS NOT BEEN REMOVED. (TRASH SHOWN IN PHOTO 4 OF PREVIOUS INSPECTION IS NO LONGER ON LOCATION). COMPLY WITH RULE 603.f. CA DATE IMMEDIATELY.**

## Inspection Photos

Location Name: STATE OF COLORADO AS 42-36V

API#: 05-071-07274

INSP. #: 695100789



**PHOTO 5: TRASH INSIDE ENGINE HOUSE. (WAS NOT NOTED ON PREVIOUS INSPECTION). COMPLY WITH RULE 603.f. CA DATE 7/4/19**

**PHOTO 6: TRASH INSIDE ENGINE HOUSE. (WAS NOT NOTED ON PREVIOUS INSPECTION). COMPLY WITH RULE 603.f. CA DATE 7/4/19**

## Inspection Photos

Location Name: STATE OF COLORADO AS 42-36V

API#: 05-071-07274

INSP. #: 695100789



**PHOTO 7: TRASH ON NORTH SIDE OF ENGINE HOUSE. (WAS NOT NOTED ON PREVIOUS INSPECTION). COMPLY WITH RULE 603.f. CA DATE 7/4/19**