

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-08150
Date: 6-4-2019



Photo 1. View of the western project area from the northwestern edge facing southward.



Photo 2. View of the eastern project area from the northern edge facing southeastward.



Photo 3. View of green plastic netting debris within the eastern cut-slope.



Photo 4. View of erosional rilling, up to 10 inches deep within the access road.