

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/04/2019

Submitted Date:

06/04/2019

Document Number:

696300230

**FIELD INSPECTION FORM**

Loc ID 330782 Inspector Name: PETRIE, ERICA On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10071  
Name of Operator: HIGHPOINT OPERATING CORPORATION  
Address: 555 17TH ST STE 3700  
City: DENVER State: CO Zip: 80202

**Findings:**

- 8 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Barber, Matt		mbarber@hpres.com	<a href="#">All Inspections</a>
Kraich, Adam		adam.kraich@state.co.us	
Singer, Sheila		ssinger@hpres.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251812	WELL	PR	11/01/2017	OW	123-19616	COLORADO ENERGY FEDERAL 14-2	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:	Adequate, wellhead signage has been updated to reflect current operator. No further action is required.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

	Type PUMP JACK		
Comment:	Barbed Wire		
Corrective Action:		Date:	

**Equipment:**

		corrective date
Type: Deadman # & Marked # 4		
Comment:		
Corrective Action:		Date:
Type: Bradenhead # 1		
Comment: Does not appear to be plumbed to surface		
Corrective Action:		Date:
Type: Prime Mover # 1		
Comment: Pump Jack engine inside housing		
Corrective Action:		Date:
Type: Pump Jack # 1		
Comment:		
Corrective Action:		Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			

Corrective Action:	Date:
--------------------	-------

--

**Inspected Facilities**

Facility ID: 251812 Type: WELL API Number: 123-19616 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<a href="#">Routine Inspection, Wellhead signage now reflects the current operator.</a>	petrie	06/04/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696300231	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4841013">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4841013</a>