

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/04/2019

Submitted Date:

06/05/2019

Document Number:

696200161

**FIELD INSPECTION FORM**

Loc ID 327361 Inspector Name: Trujillo, Aaron On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10112  
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

**Findings:**

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		regulatory@foundationenergy.com	<a href="#">All Inspections</a>
,		dnr_cogccenforcement@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246765	WELL	SI	01/01/2019	OW	123-14562	SOONER UNIT 6-21	RI
327361	LOCATION	AC			-	SOONER UNIT-68N58W 21SENW	RI

**General Comment:**

[This is a follow-up good housekeeping inspection.](#)

[This inspection is to document compliance for the following corrective actions:](#)

[603.f: Noxious weed management](#)

[Any corrective action\(s\) from previous inspections that have not been addressed are still applicable.](#)

**Location**

<b>Lease Road:</b>			
Type	Main		
comment:	Erosion degradation and sediment transport from the main east/west access road. See photos 4-5 in the attached photo document.		
Corrective Action:	Install or repair required BMPs per Rule 1002.f.	Date:	07/05/2019

Overall Good:

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 95%;" type="text"/>

**Good Housekeeping:**

Type	WEEDS		
Comment:	<p>Previous inspections documented Noxious weeds (Diffuse Knapweed, Centaurea diffuse, and Scotch Thistle, Onopordum acanthium) along access roads and location, and required operator to manage and remove.</p> <p>Operator has failed to conduct sufficient ongoing weed management. Diffuse Knapweed remains evident on location and access roads (including main access road).</p> <p>Original corrective action and date remains applicable.</p>		
Corrective Action:	Properly remove and control noxious weeds. Ongoing weed management and monitoring is required, and needs to occur in accordance to COGCC rules and regulations.	Date:	06/22/2018

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 246765 Type: WELL API Number: 123-14562 Status: SI Insp. Status: RI

Facility ID: 327361 Type: LOCATION API Number: - Status: AC Insp. Status: RI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696200162	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4841332">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4841332</a>