

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/29/2019

Submitted Date:

05/30/2019

Document Number:

697300088**FIELD INSPECTION FORM**
 Loc ID 322868 Inspector Name: Graber, Candice (Nikki) On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name     | Phone | Email                                  | Comment |
|------------------|-------|--|---------|
| Evans, Jacob     |       | jacob.evans@nblenergy.com              |         |
| Inspections, All |       | NBL_DJBU_Inspections@NB<br>LENERGY.COM |         |

**Inspected Facilities:**

| Facility ID | Type                | Status | Status Date | Well Class | API Num | Facility Name                        | Insp Status |
|-------------|---------------------|--------|-------------|------------|---------|--------------------------------------|-------------|
| 441780      | SPILL OR<br>RELEASE | CL     | 05/15/2015  |            | -       | CHESNUT G 22-3,4<br>Historical Spill | EI          |

**General Comment:**

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Photos attached to document site condition at the time of inspection.

**Location**

|                    |   |       |            |
|--------------------|---|-------|------------|
| <b>Lease Road:</b> |   |       |            |
| Type               | Access  |       |            |
| comment:           | Recent storms have carried rainwater, mud, and trash onto and over access road. |       |            |
| Corrective Action  | Comply with Rule 603.f .  | Date: | 06/08/2019 |

Overall Good: ☐**Emergency Contact Number:**

|                    |       |             |
|--------------------|-------|-------------|
| Comment:           | Good. | Date: _____ |
| Corrective Action: |       |             |

Overall Good: ☐

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |



## Environmental

### Spill/Remediation:

Comment: [Multiple monitoring wells damaged.](#)

Corrective Action: [Perform routine maintenance on monitoring wells.](#)

Date: 06/08/2019

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: Recent storms have caused large amounts of erosion and transported sediment and trash onto and off of location.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 06/11/2019

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description             | URL   |
|--------------|-------------------------|---|
| 402059333    | INSPECTION SUBMITTED    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835469">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835469</a> |
| 697300089    | Stormwater Run On       | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835466">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835466</a> |
| 697300090    | Stormwater Run Off      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835467">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835467</a> |
| 697300091    | Damaged Monitoring Well | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835468">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835468</a> |