

## Inspection Photos

Location Name: ANTELOPE 13-32

API #: 05-071-06788

INSP. #:695100782



**PHOTO 1: WELLHEAD**

## Inspection Photos

Location Name: ANTELOPE 13-32

API #: 05-071-06788

INSP. #:695100782



**PHOTO 2: WELL SIGN NOT POST AT LOCATION NO EMERGENCY CONTACT INFORMATION. THIS IS A FOLLOWUP TO PREVIOUS INSPECTION. INSP. DOC# 687902811 THIS CORRECTIVE ACTION HAS NOT BEEN ADDRESSED. **POST WELL SIGN TO COMPLY WITH 210 SERIES RULES.****

**PHOTO 3: IMAGE OF MISSING WELL SIGN FROM PREVIOUS INSPECTION DOC# 687902811.**

## Inspection Photos

Location Name: ANTELOPE 13-32

API #: 05-071-06788

INSP. #:695100782



**PHOTO 4: NO FREEBOARD MARKER. PIT DOES NOT APPEAR TO BE IN USE. NO GATHERING LINES PLUMBED TO PIT. PIT IS DRY. **INSTALL FREEBOARD MARKER IN ACCORDANCE WITH 902 SERIES RULES. CONTACT COGCC EPS STAFF REGARDING FUTURE USE OF PIT. CA DATE 6/16/19****

**PHOTO 5: IMAGE OF NO FREEBOARD MARKER IN PIT FROM PREVIOUS INSPECTION DOC# 687902811.**