

Inspection Photos  
Location Name: SALIDA 44-26  
API#: 05-071-07675  
INSP. #: 695100801



Colorado Oil & Gas Conservation Commission  
37.1368, -104.84875, 2107.0m, 234°  
2019/06/05 11:38:38



Colorado Oil & Gas Conservation Commission  
37.13691, -104.8487, 2110.0m, 266°  
2019/06/05 11:39:16

**PHOTO 1: WELLHEAD/ APPROXIMATELY 3' BY 3' AREA OF IMPACTED SOIL NEAR WELLHEAD. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907" CA DATE 7/5/19**

**PHOTO 2: WELL SIGN**

Inspection Photos  
Location Name: SALIDA 44-26  
API#: 05-071-07675  
INSP. #: 695100801



**PHOTO 3: EROSION IN DRAINAGE DITCH ON MAIN LEASE ROAD APP. 75 YARDS WEST OF LOCATION ACCESS ROAD. REPAIR DRAINAGE DITCH AND INSTALL BMP'S TO PREVENT EROSION AND SEDIMENT MIGRATION IN ACCORDANCE WITH 1002 SERIES RULES. CA DATE 7/5/19.**

**PHOTO 4: EROSION ON ACCESS ROAD JUST SOUTH OF ENTRANCE OF ACCESS ROAD. NO DRAINAGE DITCH OR BMP'S OBSERVED AT TIME OF INSPECTION. INSTALL PROPER DRAINAGE AND BMP'S IN ACCORDANCE WITH 1002 SERIES RULES. CA DATE 7/5/19**

Inspection Photos  
Location Name: SALIDA 44-26  
API#: 05-071-07675  
INSP. #: 695100801



**PHOTO 5: GUY LINE ANCHORS NOT MARKED. INSTALL GUY LINE MARKERS IN ACCORDANCE WITH 1003. SERIES RULES. CA DATE 7/5/19**

**PHOTO 6: GUY LINE ANCHORS NOT MARKED. INSTALL GUY LINE MARKERS IN ACCORDANCE WITH 1003. SERIES RULES. CA DATE 7/5/19**