

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/04/2019

Submitted Date:

06/06/2019

Document Number:

697000017

**FIELD INSPECTION FORM**

Loc ID 463974 Inspector Name: Kosola, Jason On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 35080  
Name of Operator: GRAND MESA OPERATING CO  
Address: 1700 N. WATERFRONT PKWY BL 600  
City: WICHITA State: KS Zip: 67206

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Reilly, Patrick		PReilly@gmocks.com	
Reilly, Michael	(316) 265-3000	mreilly@gmocks.com	Principal Agent
BREWER, PHYLLIS		PBrewer@GMOCKS.com	REGULATORY

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
463972	WELL	DG	05/09/2019		073-06765	GLYDE 1-15	EI

**General Comment:**

This is an environmental inspection to document status of pit.

Drilling pit contains more than de minimus amount of hydrocarbon on pit in violation of COGCC rules (see attached photos). Operator shall immediately remove free fluid from drilling pit.

This is an environmental inspection only. Any corrective actions from previous inspections that have not been addressed are still applicable. Photos attached to document site condition at the time of inspection.

**Inspected Facilities**

Facility ID: 463972 Type: WELL API Number: 073-06765 Status: DG Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Drilling Pit                      Lined: NO                      Pit ID:                      Lat: 39.437200                      Long: -103.540460

Reference Point: SE                      Other: \_\_\_\_\_                      Length: \_\_\_\_\_                      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_                      Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type: None                      Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date:

**Netting:**

Netting Type: \_\_\_\_\_                      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date:

Anchor Trench Present: \_\_\_\_\_                      Oil Accumulation: \_\_\_\_\_                      2+ feet Freeboard: \_\_\_\_\_

Comment: More than "de minimis" amount of hydrocarbons observed on pit.

Corrective Action

Remove oil from pit per Rule 902.c.

Date: 06/07/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
69700018	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4841881">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4841881</a>