

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/05/2019

Submitted Date:

06/06/2019

Document Number:

696600070**FIELD INSPECTION FORM**
 Loc ID 312610 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
Colby, Lou		lou.colby@state.co.us	All Reclamation
Hartman, Robert	970-244-3041	bhartman@blm.gov	All Inspections
, DNR		dnr_cogccengineering@state.co.us	All Engineering
Ried, Jordan	970-563-400	maralextechjr@gmail.com	All Inspections
Graves, Jim		mrinc20@qwestoffice.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222012	WELL	SI	05/01/2010	GW	077-08614	SOUTH SHALE RIDGE 5-23	TA

General Comment:

This is a follow up inspection from [Doc#675002140](#) dated 4/8/19 . Required Corrective Action (s) items noted in previous inspections have not been satisfied.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	No sign at well head at this time.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	05/10/2019

Emergency Contact Number:

Comment: 911 / 970-858-8550

Corrective Action:

Date:

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	All Production, Pump Jack, Gas Meter Run, tank and separator equipment stored on location		
Corrective Action:	Comply with Rule 603.f .	Date:	07/10/2019
Type	DEBRIS		
Comment:	Weeds and debris on location		
Corrective Action:	Comply with Rule 603.f .	Date:	10/08/2018

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	#		
Comment:	All equipment is disconnected and set aside on location		
Corrective Action:		Date:	
Type: Pump Jack	#		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	#		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
----------	---	----------	------	---------	--------	--

PRODUCED WATER	1	200 BBLs	Open Top		
Comment: fiberglass open top tank is disconnected and set to side of location.					
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected FacilitiesFacility ID: 222012 Type: WELL API Number: 077-08614 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: All production equipment has been diconenected and removed from wellhead, noted on previous inspection Doc#689400348 from 9/26/17.

No current MIT on record or delinquent as required by Rule 326c

Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan.

Date: 10/08/2018

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
		Compaction				
		Gravel				

Comment: Stormwater erosion being controlled on the location at this time.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On Wednesday) (Date 06/05/2019) at approximately (1115), I, Inspector Dougo Wentzel, conducted a (A Follow up Inspection) at (Maralex) (South Shale Ridge 5-23), at (API #077-08614) in (Mesa, county) Colorado.</p> <p>While there, I observed a (Production location operation only)</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Vegetation growth around wellhead and Debris (weeds) on location.</p> <p>Stored and unused equipment on location</p> <p>No current MIT on file.,</p> <p>(Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed compliance issue.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	06/06/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
696600071	Inspection 696600070 photos	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4841947