

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/05/2019

Submitted Date:

06/06/2019

Document Number:

696600076

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
312606 _____ Wentzel, Dougo _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|----------------------------|---------------------------------|
| Hartman, Robert | 970-244-3041 | bhartman@blm.gov | All Inspections |
| Hartman, Robert | 970-244-3041 | bhartman@blm.gov | All Inspections |
| Peicka, Conor | | conor.pesicka@state.co.us | All Inspections |
| Kellerby, Shaun | | shaun.kellerby@state.co.us | All Inspections |
| Ried, Jordan | 970-563-400 | maralextechjr@gmail.com | All Inspections |
| Graves, Jim | | mrinc20@qwestoffice.net | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 222008 | WELL | SI | 05/01/2012 | GW | 077-08610 | SOUTH SHALE RIDGE 9-17 | PA |

General Comment:

This is a follow up inspection from Doc#675002149 dated 4/9/19 . Required Corrective Action (s) items noted in previous inspections have not been satisfied.
Form 6s in progress. doc #401654713 dated 1/29/19
No corrective action from previous inspection have been made

| Location | | | |
|--|--|--------|------------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective ActionL | | Date: | |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Emergency Contact Number: | | | |
| Comment: | No signage on location | | Date: 02/11/2019 |
| Corrective Action: | Install sign to comply with Rule 210.b. | | |
| Good Housekeeping: | | | |
| Type | STORAGE OF SUPL | | |
| Comment: | Riser left unmarked, not locked out tagged out T-post in ground over a hole | | |
| Corrective Action: | Comply with Rule 603.f . | | Date: 01/11/2019 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

Facility ID: 222008 Type: WELL API Number: 077-08610 Status: SI Insp. Status: PA

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Compaction | Pass | | | |
| | | Gravel | Pass | | | |

Comment: At time of inspection stormwater Erosion appears to be controlled.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|--|----------|------------|
| <p>On Wednesday) (Date 06/05/2019) at approximately (1245), I, Inspector Dougo Wentzel, conducted a (A Follow up Inspection) at (Maralex) (South Shale Ridge 9-17), at (API #077-08610) in (Mesa, county) Colorado.</p> <p>While there, I observed a (Production location operation only) During this inspection the following possible compliance issues were observed: Vegetation growth on entire location A unmarked Riser in a hole on location Two t-post stuck in what looks like a rodent hole on location. Well plugged on 10/16/17. Form 6 (s) Doc#401654713 No equipment on location other than one riser. (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if correction actions are identified) This is a summary of inspection report.</p> | wentzeld | 06/05/2019 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------------|---|
| 696600077 | Inspection 696600076 photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4841950 |