

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/05/2019

Submitted Date:

06/06/2019

Document Number:

696600072

FIELD INSPECTION FORM

Loc ID 312611 Inspector Name: Wentzel, Dougo On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Findings:

- 8 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hartman, Robert	970-244-3041	bhartman@blm.gov	All Inspections
Ried, Jordan	970-563-400	maralextechjr@gmail.com	All Inspections
Graves, Jim		mrinc20@qwestoffice.net	
Colby, Lou		lou.colby@state.co.us	All Reclamation
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222013	WELL	SI	05/01/2012	GW	077-08615	SOUTH SHALE RIDGE 9-22	PA

General Comment:

This is a follow up inspection from [Doc#675002143](#) dated 4/9/19 . Required Corrective Action (s) items noted in previous inspections have been satisfied.

Location

Lease Road:

Type Access

comment:

Corrective ActionL

Date:

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 222013 Type: WELL API Number: 077-08615 Status: SI Insp. Status: PA

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: All equipment and pipe risers have been removed. Nothing on location
At time of inspection stormwater Erosion appears to be controlled.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On Wednesday) (Date 06/05/2019) at approximately (1155), I, Inspector Dougo Wentzel, conducted a (A Follow up Inspection) at (Maralex) (South Shale Ridge 9-22), at (API #077-08615) in (Mesa, county) Colorado.</p> <p>While there, I observed a (Production location operation only) Only Vegetation growth on location Stored and unused equipment on location has been removed. Form 6 filed and in progress dated 4/30/19 # 402026760 (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	06/06/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696600073	Inspection 696600072 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4841948