

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/05/2019

Submitted Date:

06/06/2019

Document Number:

689703193**FIELD INSPECTION FORM**Loc ID 335999 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only
Kellerby, Shaun		shaun.kellerby@state.co.us	

General Comment:COGCC Inspection Report Summary

On Wednesday 06/05/2019 at approximately 1400 hrs, I, Inspector Mike Longworth, conducted a field inspection at Caerus CHEVRON-65S96W 596-31C Location id # 335999 in Garfield County, Colorado.

While there, I observed Production

During this inspection the following possible compliance issues were observed:

Label on container at well is faded and illegible.

Install sign to comply with Rule 210.d. C.A. Date 08/06/2019

Well signs not maintained. No sign found at 26. Sign for 31C can not be read. Signs laying down at wells or in well cellars.

Install sign to comply with Rule 210.b. C.A. Date 08/06/2019

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Label on container at well is faded and illegible.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	08/06/2019
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Sign is weathered and becoming illegible.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well signs not maintained. No sign found at 26. Sign for 31C can not be read. Signs laying down at wells or in well cellars.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	08/06/2019

Emergency Contact Number:

Comment: 970-285-2615

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
				Material Handling And Spill Prevention	Pass	
		Ditches	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689703198	Inspection 689703193 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4842111