

Location

Overall Good:

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|---|-------|------------|
| Emergency Contact Number: | | | |
| Comment: | Emergency Contact Number is fading. | | |
| Corrective Action: | Install sign to comply with Rule 210.b. | Date: | 07/01/2019 |

| | | | |
|---------------------------|-----------------------------|-------|------------|
| Good Housekeeping: | | | |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused 2" pipe at wellhead. | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 07/01/2019 |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------|----------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 259305 Type: WELL API Number: 123-20294 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary On Tuesday 05/28/2019 at approximately 12:02 PM, I, Inspector Erica Petrie, conducted a field inspection at PDC Energy INC, Wacker 10-D at Location #331196 in Weld, Colorado. While there, I observed Type of Operation: Production During this inspection the following possible compliance issues were observed: Emergency Contact Number is fading, See Photo #1, CA date 07/01/2019 Unused 2" pipe, See Photo #1, CA 07/01/2019 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> | petrie | 05/31/2019 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402061544 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4837346 |
| 696300216 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4837344 |