

Caerus Piceance LLC  
API # 05-077-09239  
Inspection # 696600095



**Photo #1 Photo from entrance location**

Caerus Piceance LLC  
API # 05-077-09239  
Inspection # 696600095



Photo #2 tank battery , one tank removed leaving rust stain inside containment.



Photo#3 @ wellheads on location one hooked up to rig for PA other is TA

Caerus Piceance LLC  
API # 05-077-09239  
Inspection # 696600095



**Photo #4 Photo of site location where production equipment has been removed. Risers are not locked out tagged out**