

Encana
API # 05-077-10208
Inspection # 696600097



Photo #1 Photo from entrance of location. Caerus plugging operation taking place