

Caerus Piceance LLC
API # 05-077-09168
Inspection # 696600099



Photo #1 Photo from entrance of location. (Battery sign missing information. Laying over and damaged.)

Caerus Piceance LLC
API # 05-077-09168
Inspection # 696600099



Photo #2 Photo taken from entrance of location.

Photo #3 Photo taken of tank battery

Caerus Piceance LLC
API # 05-077-09168
Inspection # 696600099



Photo 4 Photo of wellhead with sign

Photo 5, Photo of separators with signs