

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/07/2019

Submitted Date:

06/09/2019

Document Number:

679704399**FIELD INSPECTION FORM**Loc ID 315214 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor	970-415-0789	conor.pesicka@state.co.us	
Energy, Foundation		regulatory@foundationenergy.com	Regulatory
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	
Arauza, Steven		steven.arauza@state.co.us	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230425	WELL	SI	07/01/2016	GW	103-08088	TAIGA FED 9J-21-4-102	SI

General Comment:[COGCC Inspection Report Summary.](#)

On 6-7-2019 at approximately 14:00, inspector Rick Moran, conducted a routine inspection at Foundation Energy Management's well Taiga Federal 9-J-21-4S-102W in Rio Blanco county.

During this inspection the following compliance issues were observed:

- 1) Extra well head signs from old operator(s). Photo 2. Correct by 8-6-2019.
- 2) Battery sign with previous operator. Photo 3. Correct by 8-6-2019.
- 3) No blowdown tank label. Photo 4. Correct by 8-6-2019.
- 4) Blowdown tank pushed over and fluid spill. Correct by 7-8-2019.
- 5) No current MIT.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679704399.

Location

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Sign not updated to reflect current operator.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	08/06/2019
Type	TANK LABELS/PLACARDS		
Comment:	No tank sign present.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	08/06/2019
Type	WELLHEAD		
Comment:	Remove previous operator well head signs. Current operator well sign is present.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	08/06/2019

Emergency Contact Number:

Comment: 866-767-3600

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	
Produced Water	Tank		
Comment:	Smell of condensate present in water.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 07/08/2019

In Containment: Yes

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	BV FIBERGLASS		39.682800,-108.845080
Comment:	<p>Tank is lying partially on side. Hole in the side of the tank is present. Fluid level on the inside of the tank coincides with the hole. Fluid present outside and under the tank. 2 of 4 tank anchors are pulled out of the ground. Cattle prints next to tank.</p> <p>Bulls observed next to lease road 0.2 miles away.</p>				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 230425 Type: WELL API Number: 103-08088 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: [Last recorded production June 2016. No MIT on file.](#)[No current MIT on record or delinquent as required by Rule 326](#)

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No apparent soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679704400	inspection photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4844245