

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/10/2019

Submitted Date:

06/10/2019

Document Number:

690101269

**FIELD INSPECTION FORM**Loc ID 320426 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10454

Name of Operator: PETROSHARE CORPORATION

Address: 9635 MAROON CIRCLE #400

City: ENGLEWOOD State: CO Zip: 80112

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
Silver, Randy		randy.silver@state.co.us	
Lloyd, Bill		blloyd@petrosharecorp.com	
Brown, Devin	(303)-349-0302	dbrown@petrosharecorp.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203732	WELL	TA	07/01/2018	GW	001-09292	WYMAN 34-6	EG

**General Comment:**

Followup COGCC (EG) Field Inspection; The Corrective Actions outlined on COGCC FIR doc #690100417 dated 04/09/2018 have been completed by the operator. This well has been plugged and abandoned/ facilities removed. Photos uploaded.

Inspected Facilities									
Facility ID:	203732	Type:	WELL	API Number:	001-09292	Status:	TA	Insp. Status:	EG

--

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Spill/Remediation:**

Comment: [Corrective Action Required Completed:](#)  
[Operator has Submitted COGCC Form 27 per Rule 905.b. \(approved retroactively\).](#)  
[The resulting remediation project \(REM 11228\) was closed on 08/22/2018.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101271	Location photo (view west)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845555">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845555</a>
690101272	Signage at lease road	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845556">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845556</a>