

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/11/2019

Submitted Date:

06/11/2019

Document Number:

687904898**FIELD INSPECTION FORM**Loc ID 322097 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100178Name of Operator: D J SIMMONS INCAddress: P.O. BOX 1469City: FARMINGTON State: NM Zip: 87499**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Rabinowitz, Daniel	970-385-1363	drabinow@blm.gov	Durango
Telecky, Barbara		btelecky@blm.gov	Durango
Seale, Rod		rseale@djsimmons.com	Pet. Eng./Operations Mgr

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208959	WELL	PR	03/01/2019	GW	033-06064	RANGER-FEDERAL 24-7	PR

General Comment:[Site inspection with photos at the end of this report.](#)

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign posted on meter house door.		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	Contact information posted on sign.
Corrective Action:	Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	On separator stack.		
Corrective Action:		Date:	
Type: Flow Line	# 4		
Comment:	1-2" flowline from wellhead to separator. 1-2" flowline from separator dump to offsite gathering system. 1-2" flowline from separator to meter house. 1-2" flowline from meter house to offsite gathering system.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:		
Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:	
Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities				
Facility ID: 208959	Type: WELL	API Number: 033-06064	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing.			
Corrective Action:				Date:

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Ditches	Pass					
Berms	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687904899	Location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845754
687904900	Meter house.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845755
687904901	Separator.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845756