

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/05/2019

Submitted Date:

06/11/2019

Document Number:

688800532

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
Hughes, Jim _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10515
 Name of Operator: GUNNISON ENERGY LLC
 Address: 1801 BROADWAY #1150
 City: DENVER State: CO Zip: 80202

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Roy, Catherine		catherine.roy@state.co.us	
Stranathan, Thane		tstranat@blm.gov	Gunnison County Inspections
Donahue, Jessica		Jessica.Donahue@oxbow.com	
Heil, John		john.heil@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451553	SPILL OR RELEASE	CL	08/17/2017		-	Deadman Gulch Unit	EI

General Comment:

On June 5, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Gunnison Energy LLC Spill/Release Point ID #451553. For the most recent field inspection report of this facility, please refer to document #688800309. Thane Stranathan from the Montrose BLM office was present during this field inspection.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	Steel barricade around pipeline risers.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Post and wire fencing around perimeter of project area.		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Other	# 2		
Comment:	Valve can with gas and water gathering line vent risers.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 451553 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Environmental

Spill/Remediation:

Comment: [Please refer to REM Project #10395 for more information regarding the remediation and reclamation of Spill/Release Point ID #451553.](#)

Corrective Action:

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Blankets	Pass					
Slope Roughening	Pass					
Other	Pass					Water bars along ROW.
Seeding	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On June 5, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Gunnison Energy LLC Spill/Release Point ID #451553. For the most recent field inspection report of this facility, please refer to document #688800309. Thane Stranathan from the Montrose BLM office was present during this field inspection. This follow up inspection was conducted to assess the condition of remediation work associated with REM Project #10395. The reclaimed area remains fenced off.	hughesjo	06/11/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800533	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4846295