

Inspection Photos

Loc#334828

Operator: Caerus

Insp#692401083

Inspection Date: 5/31/2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to North.

May 31, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus GMU Loc#334828



Photo#2:
Staining at Wellhead.

May 31, 2019



Photo#3:
Subsidence at Wellhead.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus GMU Loc#334828



Photo#4:
Subsidence at Culvert area.

May 31, 2019



Photo#5:
Subsidence at Culvert area.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus GMU Loc#334828



Photo#6:
Sediment migration from access Road.

Photo#7:
Sediment migration from access Road.

May 31, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus GMU Loc#334828



Photo#8:
Vegetation is well established.

May 31, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus GMU Loc#334828