

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/05/2019

Submitted Date:

06/11/2019

Document Number:

688800536

**FIELD INSPECTION FORM**Loc ID 424290 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10515

Name of Operator: GUNNISON ENERGY LLC

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Stranathan, Thane		tstranat@blm.gov	Gunnison County Inspections
Donahue, Jessica		Jessica.Donahue@oxbow.com	
Heil, John		john.heil@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421193	CENTRALIZED EP WASTE MGMT FAC	AC	01/18/2011		-	HOTCHKISS WATER STORAGE FACILITY 421193	EI
454880	PIT	AC			-	HWSF-Southern Pit	EI
454881	PIT	AC			-	HWSF-Northern Pit	EI

**General Comment:**

On June 5, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Gunnison Energy LLC Hotchkiss Water Storage Facility. For the most recent field inspection report of this facility, please refer to document #688800309. Thane Stranathan from the Montrose BLM office was present during this site visit.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Open topped frac tank has labels and placard.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Facility sign mounted to entrance gate.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Posted on location sign.

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Chain link perimeter fencing.		
Corrective Action:		Date:	
Type	PIT		
Comment:	Pits are fenced and netting is in place.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Pump house.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Filter shack.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Natural gas powered generator and electrical supply panel.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	Open Top		39.019564,-107.375607
Comment:					

Corrective Action:		Date:	
<b>Paint</b>			
Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			
<b>Berms</b>			
Type	Capacity	Permeability (Wall)	Permeability (Base)
Comment:			
Corrective Action:		Date:	
<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: <u>421193</u>	Type: <u>CENTRALIZE</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>
----------------------------	-------------------------	----------------------	-------------------	-------------------------

Facility ID: <u>454880</u>	Type: <u>PIT</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>
----------------------------	------------------	----------------------	-------------------	-------------------------

Facility ID: <u>454881</u>	Type: <u>PIT</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>
----------------------------	------------------	----------------------	-------------------	-------------------------

## Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts	Pass					
Waddles	Pass					
Ditches	Pass	Compaction	Pass			
Sediment Traps	Pass					
Rip Rap	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Multiwell Reuse/ RecyclingLined: YESPit ID: 454881Lat: 39.020150Long: -107.376300Reference Point: SEOther: Length: Width: **Lining:**Liner Type: HDPELiner Condition: InadequateComment: Northern PitCorrective Action: Date: **Fencing:**Fencing Type: Netting/Fence.comFencing Condition: AdequateComment: Corrective Action: Date: **Netting:**Netting Type: Fence/Net ComboNetting Condition: GoodComment: Corrective Action: Date: Anchor Trench Present: YESOil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Action: Date: Type: Multiwell Reuse/ RecyclingLined: YESPit ID: 454881Lat: 39.020150Long: -107.376300Reference Point: Other: Length: Width: **Lining:**Liner Type: HDPELiner Condition: InadequateComment: An area with the pit liner exposed above the surface of the fluid level in the southern pit was observed during this inspection.Corrective Action: Date: **Fencing:**Fencing Type: Netting/Fence.comFencing Condition: Adequate

Inspector Name: Hughes, Jim

Comment:		Date:
Corrective Action		
<b>Netting:</b>		
Netting Type: <u>Fence/Net Combo</u>	Netting Condition: <u>Good</u>	
Comment:		Date:
Corrective Action		
Anchor Trench Present: <u>YES</u>	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:		Date:
Corrective Action		

**COGCC Comments**

Comment	User	Date
On June 5, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Gunnison Energy LLC Hotchkiss Water Storage Facility. For the most recent field inspection report of this facility, please refer to document #688800309. Thane Stranathan from the Montrose BLM office was present during this site visit. During this site visit, part of the southern pit liner was observed above the fluid level. An inquiry to the operator is pending further investigation. Samples have reportedly been collected from the monitoring well locations, the pit, and the leak detection system.	hughesjo	06/11/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800537	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4847091">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4847091</a>