

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/07/2019

Submitted Date:

06/12/2019

Document Number:

688304829**FIELD INSPECTION FORM**
 Loc ID 317040 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 95620Name of Operator: WESTERN OPERATING COMPANYAddress: 1165 DELAWARE STREET #200City: DENVER State: CO Zip: 80204**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:21 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
James, Steve	(303) 893-2438	steve@westernoperating.com	President
Crumley, Tim	(970) 768-5659	tcrumley@comcast.net	
Reid, Marta	(303) 893-2438	marta@westernoperating.com	Designated Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
234850	WELL	PR	08/01/2014	OW	121-06991	G O YEAMANS 1	PR

General Comment:

Routine Inspection

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	lease sign at CR DD		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 303-893-2483

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	stained soil at muffler (see attached photo)		
Corrective Action:		Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	tin shed for engine, steel panels		
Corrective Action:		Date:	

Equipment:

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 3	
Comment:	lid on fiberglass tank missing (see attached photo)	
Corrective Action:	Install or repair wildlife protection equipment.	Date: 06/26/2019
Type: Prime Mover	# 1	
Comment:	gas engine, propane, shed	
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:	2 chemical containers	
Corrective Action:		Date:
Type: Vertical Heater Treater	# 1	
Comment:	shed, bermed	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.143380,-103.184640
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				

Comment:		animal holes in berms (see attached photo)					
Corrective Action:		Install or repair required BMPs per Rule 1002.f.				Date: 07/12/2019	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	1	300 BBLs	HEATED STEEL AST		,		
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition							
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:		same berms as unheated crude oil tank					
Corrective Action:						Date:	
<u>Venting:</u>							
Yes/No	YES						
Comment:							
Corrective Action:					Date:		
<u>Flaring:</u>							
Type							
Comment:							
Corrective Action:					Date:		

Location Construction

Location ID: 234850 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: No COAs.

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities									
Facility ID:	234850	Type:	WELL	API Number:	121-06991	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR. Feb 2019 production reported to COGCC database.								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: dryland crop fieldCorrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment: west pit, after tankCorrective Action: Date: Type: Produced WaterLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: dryland crop fieldCorrective Action: Date: **Netting:**Netting Type: Netting Condition:

Comment:					Date:
Corrective Action					
Anchor Trench Present:		Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>		
Comment:	<u>east pit, check pit berm compaction on east side of pit (see attached photo), may also be sediment from field</u>				Date:
Corrective Action					
Type: <u>Produced Water</u>	Lined: <u>NO</u>	Pit ID:	Lat:	Long:	
Reference Point:	Other:	Length:	Width:		
<u>Lining:</u>					
Liner Type:		Liner Condition:			
Comment:					Date:
Corrective Action					
<u>Fencing:</u>					
Fencing Type: <u>None</u>		Fencing Condition:			
Comment:	<u>dryland crop field</u>				Date:
Corrective Action					
<u>Netting:</u>					
Netting Type:		Netting Condition:			
Comment:					Date:
Corrective Action					
Anchor Trench Present:		Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>		
Comment:	<u>middle pit</u>				Date:
Corrective Action					

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688304856	Western Operating G O Yeamans 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4847222