

Inspection Photos

API: 05-055-06012

Operator: OXY USA INC

Inspection Date: 6/11/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-055-06012 | Date: 6/11/2019

Inspection Photos



Photo 1. The operator name on well sign is not legible.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06012 | Date: 6/11/2019

Inspection Photos



Photo 2. Facing east toward the pit at the location. There is staining that remains which was observed in the previous inspection and has not been cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06012 | Date: 6/11/2019

Inspection Photos



Photo 3. View of stained soil with strong hydrocarbon odor.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06012 | Date: 6/11/2019

Inspection Photos



Photo 4. There are List B noxious weeds along the western side of the pit. Canada thistle and Houndstongue.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06012 | Date: 6/11/2019

Inspection Photos



Photo 5. View of stained soils at the back side of the tanks.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06012 | Date: 6/11/2019

Inspection Photos



Photo 6. There is a bent bucket for secondary containment at the discharge point of the tank.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06012 | Date: 6/11/2019