

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/11/2019

Submitted Date:

06/11/2019

Document Number:

692602007

FIELD INSPECTION FORM

Loc ID 304960 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|-------|---------------------------------|---------|
| Beard, Alyssa | | regulatory@foundationenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 277073 | WELL | PR | 03/09/2005 | GW | 125-09201 | ROSE 33-18 | PR |

General Comment:

Routine Inspection

Location

| | | | |
|--------------------|---------------------------|--|-------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Trail through farm ground | | |
| Corrective ActionL | | | Date: |

Overall Good:

| | | | |
|----------------------|-------------------------------|--|-------|
| Signs/Marker: | | | |
| Type | OTHER | | |
| Comment: | Lease sign by water tank | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | Lease sign by fiberglass shed | | |
| Corrective Action: | | | Date: |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Metal sign by water tank | | |
| Corrective Action: | | | Date: |

| | | | |
|----------------------------------|--|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |

Overall Good:

| Spills: | | | |
|----------------|------|--------|--|
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------------|---|--|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Vertical Separator | # 1 | | |
| Comment: | Vertical gas separator in fiberglass shed | | |
| Corrective Action: | | | Date: |

| Tanks and Berms: | | | | | |
|-------------------------|---|----------|----------------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | OTHER | PBV FIBERGLASS | | 39.880110,-102.229120 |
| Comment: | Fiberglass water tank 50% buried 500' S of wellhead | | | | |
| Corrective Action: | | | | | Date: |

| | |
|--------------|--|
| Paint | |
| Condition | |

| | |
|--------------------------|--|
| Other (Content) | |
| Other (Capacity) 210bbbs | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| Yes/No | NO | | |
|--------------------|----|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 277073 Type: WELL API Number: 125-09201 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Central meter run for \(Rose 1-18, 3-18, 4-18, 13-18, 22-18, 23-18, 24-18, 32-18, 33-18, 43-18, 44-18, Shay 11-18\) 800' SSE @ Rose 1-18](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Other | Pass | Other | Pass | | | |

Comment: Location and access are farmed over. Main access along farm ground has erosion and needs maintenance

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT