

**Inspection Photos**  
**Location Name:** DRYER-67N60W /14NWNW  
**Location #:** 306577



**Photo #1**  
**Dryer #1 (05-123-24938) Wellsite**  
**Shut-In | SI**



**Photo #2**  
**April 12-14, Dryer #1 Battery**  
**Shut-down**



**Inspection Photos**  
**Location Name:** DRYER-67N60W /14NWNW  
**Location #:** 306577



**Photo #3**  
**Dryer #1 Wellsite**

*Bradenhead does NOT appear plumbed to surface  
from prior insp.*



**Photo #4**  
**Dryer #1 Wellsite**

*Bradenhead NOW appears plumbed to surface*



**Inspection Photos**  
**Location Name:** DRYER-67N60W /14NWNW  
**Location #:** 306577



**Photo #5**  
**Dryer #1** Engine house  
*Stained soil near engine base  
from prior insp.*



**Photo #6**  
**Dryer #1** Engine house  
*Stained soil near engine base – Appears mitigated*

**Inspection Photos**  
**Location Name:** DRYER-67N60W /14NWNW  
**Location #:** 306577



**Photo #7**  
**Dryer #1 Pumpjack**  
*Gearbox stain & apparent seepage  
from prior insp.*



**Photo #8**  
**Dryer #1 Pumpjack**  
*Gearbox stain & apparent seepage  
Appears mitigated*



**Inspection Photos**  
**Location Name:** DRYER-67N60W /14NWNW  
**Location #:** 306577



**Photo #9**  
**Dryer #1** Wellsite  
*Unused equipment (belt guard)*  
*55-gal. Drum, labeling / placard appears illegible*  
*from prior insp.*



**Photo #10**  
**Dryer #1** Wellsite  
*Unused equipment (belt guard) - Removed*  
*55-gal. Drum, labeling / placard appears Legible*