

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/12/2019

Submitted Date:

06/12/2019

Document Number:

696101019

**FIELD INSPECTION FORM**
 Loc ID 317498 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 76840

Name of Operator: SCHNEIDER ENERGY SERVICES INC

Address: P O BOX 889

City: FORT MORGAN State: CO Zip: 80701

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

17 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Schneider, Jeff	(970) 867-9437	jeff@schneiderenergy.com	President
Bothwell, Kevin	(970) 867-9437	kevin@schneiderenergy.com	Vice-President

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
111647	PIT	AC	09/23/1999		-	APRIL 12-14	AC
238513	WELL	SI	09/01/2018	OW	123-05372	APRIL 12-14	SI

**General Comment:**

This is a WELL & BATTERY inspection.  
Well is Shut-In (SI).  
Battery & ALL equipment is Shut-down.  
Centralized Battery serves 2 Location IDs (317498, 306577).  
(2 - wells ; Shut-In - SI).  
Follow-up to Field Inspection Report Doc. #691200345 dated 08/17/2018.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	<p>Prior insp:            Unused Equipment at Battery site.            Unused steps &amp; walkway from previously removed tanks lying on ground.            Refer to Rule 603.f for guidance. Remove unused steps &amp; walkway at Battery site.            Comply w/ Rule 603.f.            Original Corrective Action date: 09/19/2018.            This insp:            * Unused steps &amp; walkway at Battery site NOW removed.            See photos #3, 4.</p>		
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Iron pipe.		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date	
Type: Prime Mover	# 1				
Comment:	Gas engine.				
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 1				
Comment:	Prior insp: Stained soil underneath horizontal heated separator. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d. Remove or remediate stained soil. Comply w/ Rule 605.d. Original Corrective Action date: 09/19/2018. This insp: * Stained soil underneath horizontal heated separator NOW appears mitigated. See photos #7-10.				
Corrective Action:				Date:	
Type: Bradenhead	# 1				
Comment:	Appears plumbed to surface.				
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:				Date:	
Type: Deadman # & Marked	# 4				
Comment:	4/4				
Corrective Action:				Date:	
Type: Bird Protectors	# 1				
Comment:					
Corrective Action:				Date:	
Type: Pump Jack	# 1				
Comment:					
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 2 Location IDs (317498, 306577).				
Corrective Action:				Date:	

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	1	300 BBLs	STEEL AST		40.577190,-104.066593		
Comment:		<p>Prior insp:  East crude oil tank appears stained.  Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.  Remediate stained east crude oil tank. Comply w/ Rule 605.d.  Original Corrective Action date: 09/19/2018.  This insp:  * Stain on East crude oil tank NOW appears mitigated.  See photos #5, 6.</p>					
Corrective Action:				Date:			

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:		Shares berms w/ 300 Bbls. condensate tank.			
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:		Shares berms w/ 300 Bbls. crude oil tank.			
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 111647 Type: PIT API Number: - Status: AC Insp. Status: ACFacility ID: 238513 Type: WELL API Number: 123-05372 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: Shut-In (SI). Observed production valves closed.  
COGCC records indicate last prod: 08/2018.Corrective Action:  Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 111647Lat: 40.577140Long: -104.067103Reference Point: SE

Other: \_\_\_\_\_

Length: 40Width: 25**Lining:**

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**Netting Type: MeshNetting Condition: Good

Comment:

Prior insp:  
 Gaps in mesh netting over first pit. Gaps in the netting & underneath frame.  
 First pit has hydrocarbon accumulation on water with stained soil.  
 Remove oil from pit per Rule 902.c.  
 Maintain net or fence pit to prevent access per rule 902.d.  
 Original Corrective Action date: 08/21/2018.  
 This insp:  
 \* Oil appears mitigated from water and soil on first pit.  
 Gaps in mesh netting and underneath frame on first pit appears mitigated.  
 See photos #11-14.

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation: NO2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 06/12/2019 at approximately 12:22 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: SCHNEIDER ENERGY SERVICES INC  Location Name: APRIL-67N60W /14SWNW  Location ID: 317498  Location County: Weld County, Colorado  Weather: Dry</p> <p>While there, I observed: Well(s) - 1: Well is Shut-In (SI).  Battery &amp; ALL equipment is Shut-down.  Centralized Battery serves 2 Location IDs (317498, 306577).  (2 - wells ; Shut-In - SI).  Follow-up to Field Inspection Report Doc. #691200345 dated 08/17/2018.  4 of 4 Corrective Actions appears addressed.  1.) Unused Equipment at Battery site.  Unused steps &amp; walkway from previously removed tanks lying on ground.  Refer to Rule 603.f for guidance. Remove unused steps &amp; walkway at Battery site.  Comply w/ Rule 603.f.  Original Corrective Action date: 09/19/2018.  * Unused steps &amp; walkway at Battery site NOW removed.  See photos #3, 4.  2.) Stained soil underneath horizontal heated separator.  Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.  Remove or remediate stained soil. Comply w/ Rule 605.d.  Original Corrective Action date: 09/19/2018.  * Stained soil underneath horizontal heated separator NOW appears mitigated.  See photos #7-10.  3.) East crude oil tank appears stained.  Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.  Remediate stained east crude oil tank. Comply w/ Rule 605.d.  Original Corrective Action date: 09/19/2018.  * Stain on East crude oil tank NOW appears mitigated.  See photos #5, 6.  4.) Gaps in mesh netting over first pit. Gaps in the netting &amp; underneath frame.  First pit has hydrocarbon accumulation on water with stained soil.  Remove oil from pit per Rule 902.c.  Maintain net or fence pit to prevent access per rule 902.d.  Original Corrective Action date: 08/21/2018.  * Oil appears mitigated from water and soil on first pit.  Gaps in mesh netting and underneath frame on first pit appears mitigated.  See photos #11-14.</p> <p>NO - NEW Corrective Actions observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	06/12/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101020	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4848433">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4848433</a>