

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/12/2019

Submitted Date:

06/12/2019

Document Number:

696101021

FIELD INSPECTION FORMLoc ID 306577 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 76840

Name of Operator: SCHNEIDER ENERGY SERVICES INC

Address: P O BOX 889

City: FORT MORGAN State: CO Zip: 80701

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Bothwell, Kevin	(970) 867-9437	kevin@schneiderenergy.com	Vice-President
Schneider, Jeff	(970) 867-9437	jeff@schneiderenergy.com	President

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289838	WELL	PR	10/01/2018	OW	123-24938	DRYER 1	SI

General Comment:

This is a WELL inspection.
Well is Shut-In (SI).
Battery & ALL equipment is Shut-down.
Centralized Battery serves 2 Location IDs (317498, 306577).
(2 - wells ; Shut-In - SI).
Refer to Field Inspection Doc #696101019 and/or Location ID #317498 for Battery /
Facility, Equipment info.
Follow-up to Field Inspection Report Doc. #691200347 dated 08/17/2018.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	CONTAINERS		
Comment:	<p>Prior insp: Container label / placarding appears illegible at wellsite. Refer to Rule 210.e. Post legible container label / placarding at wellsite. Comply w/ Rule 210.e. Original Corrective Action date: 10/19/2018.</p> <p>This insp: * Legible container label / placarding NOW posted at wellsite. See photos #9, 10.</p>		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	<p>Prior insp: Unused Equipment at wellsite. Unused pumpjack beltguard lying on ground at wellsite. Refer to Rule 603.f for guidance. Remove unused pumpjack beltguard lying on ground at wellsite. Comply w/ Rule 603.f. Original Corrective Action date: 09/19/2018.</p> <p>This insp: * Unused pumpjack beltguard lying on ground at wellsite NOW removed. See photos #9, 10.</p>		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Iron mesh panel.		

Corrective Action:				Date:	
Equipment:				corrective date	
Type: Deadman # & Marked		# 4			
Comment: 4/4					
Corrective Action:				Date:	
Type: Prime Mover		# 1			
Comment:		<p>Gas engine. Prior insp: Stained soil appears around pumpjack gas engine base. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d. Remove or remediate stained soil. Comply w/ Rule 605.d. Original Corrective Action date: 09/19/2018.</p> <p>This insp: * Stained soil around pumpjack gas engine base NOW appears mitigated. See photos #5, 6.</p>			
Corrective Action:				Date:	
Type: Other		#			
Comment:		Refer to Field Inspection Doc #696101019 and/or Location ID #317498 for Battery / Facility, Equipment info.			
Corrective Action:				Date:	
Type: Bradenhead		# 1			
Comment:		<p>Prior insp: Bradenhead does NOT appear plumbed to surface. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d. Plumb bradenhead to surface. Comply w/ Rule 605.d. Original Corrective Action date: 09/19/2018.</p> <p>This insp: * Bradenhead NOW appears plumbed to surface. See photos #3, 4.</p>			
Corrective Action:				Date:	
Type: Pump Jack		# 1			
Comment:		<p>Prior insp: Pumpjack gearbox appears stained with oil seepage. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d. Remediate stained equipment. Comply w/ Rule 605.d. Original Corrective Action date: 09/19/2018.</p> <p>This insp: * Pumpjack gearbox stained with oil seepage NOW appears mitigated. See photos #7, 8.</p>			
Corrective Action:				Date:	
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.577190,
Comment:		Centralized Battery serves 2 Location IDs (317498, 306577). Refer to Field Inspection Doc #696101019 and/or Location ID #317498 for Battery / Facility, Equipment info.			

Corrective Action:		Date:	
Paint			
Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			
Berms			
Type	Capacity	Permeability (Wall)	Maintenance
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 289838 Type: WELL API Number: 123-24938 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDS

Comment: Shut-In (SI). Observed production valves closed.
COGCC records indicate last prod: 12/2018.

Corrective Action: Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary: On WED 06/12/2019 at approximately 14:02 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: SCHNEIDER ENERGY SERVICES INC Location Name: DRYER-67N60W /14NWNW Location ID: 306577 Location County: Weld County, Colorado Weather: Dry</p> <p>While there, I observed: Well(s) - 1: Well is Shut-In (SI). Battery & ALL equipment is Shut-down. Centralized Battery serves 2 Location IDs (317498, 306577). (2 - wells ; Shut-In - SI). Refer to Field Inspection Doc #696101019 and/or Location ID #317498 for Battery / Facility, Equipment info.</p> <p>Follow-up to Field Inspection Report Doc. #691200347 dated 08/17/2018. 5 of 5 Corrective Actions appears addressed. 1.) Container label / placarding appears illegible at wellsite. Refer to Rule 210.e. Post legible container label / placarding at wellsite. Comply w/ Rule 210.e. Original Corrective Action date: 10/19/2018. * Legible container label / placarding NOW posted at wellsite. See photos #9, 10. 2.) Unused Equipment at wellsite. Unused pumpjack beltguard lying on ground at wellsite. Refer to Rule 603.f for guidance. Remove unused pumpjack beltguard lying on ground at wellsite. Comply w/ Rule 603.f. Original Corrective Action date: 09/19/2018. * Unused pumpjack beltguard lying on ground at wellsite NOW removed. See photos #9, 10. 3.) Pumpjack gearbox appears stained with oil seepage. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d. Remediate stained equipment. Comply w/ Rule 605.d. Original Corrective Action date: 09/19/2018. * Pumpjack gearbox stained with oil seepage NOW appears mitigated. See photos #7, 8. 4.) Stained soil appears around pumpjack gas engine base. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d. Remove or remediate stained soil. Comply w/ Rule 605.d. Original Corrective Action date: 09/19/2018. * Stained soil around pumpjack gas engine base NOW appears mitigated. See photos #5, 6. 5.) Bradenhead does NOT appear plumbed to surface. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d. Plumb bradenhead to surface. Comply w/ Rule 605.d. Original Corrective Action date: 09/19/2018. * Bradenhead NOW appears plumbed to surface. See photos #3, 4.</p> <p>NO - NEW Corrective Actions observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	06/12/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101022	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4848434

