

Interim Reclamation Inspection

June 12, 2019

Operator: EXTRACTION OIL & GAS LLC- #10459

Location ID: 426721

Inspection Document #: 697500197

Weld County, CO

NENE Section 35 T7N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Hergert /35-D Facility
Location ID: 426721



Photo 1. Photo taken from the northern interim area, facing East. Appears the Operator has performed the previous corrective action. Operator shall continue to monitor and manage this site until the location meets Rule 1003 standards, including weed management.



Photo 2. Photo taken from the northeastern interim area, facing West. See comments under Photo 1.

Inspection Photos
Location Name: Hergert /35-D Facility
Location ID: 426721



Photo 3. Photo taken from the southwestern location, facing West. Operator has made repairs to the erosion but the fill slope has not been properly stabilized. Straw mulch and germination was observed throughout portions of the western fill slope- see Photo 5- but not where erosion was repaired.

Inspection Photos
Location Name: Hergert /35-D Facility
Location ID: 426721



Photo 4. Photo taken from the southern location, facing East. Operator has made repairs to the erosion but the fill slope has not been properly stabilized. Appears the southern fill slope has been seeded but there was no observed mulch or other BMP to stabilize the fill slope until successful germination or establishment of vegetation.

Inspection Photos
Location Name: Hergert /35-D Facility
Location ID: 426721



Photo 5. Photo taken from the southwestern location, facing North. Operator has only made repairs to the erosion but has not implemented additional BMPs to prevent sediment laden stormwater from leaving location. Sediment laden stormwater will continue to leave the Location because the Operator has not implemented sufficient long-term stormwater BMPs.

Inspection Photos
Location Name: Hergert /35-D Facility
Location ID: 426721



Photo 6. Photo taken from the southwestern location, facing East. See comments under Photo 5.

Note: Kochia is starting to germinate along portions of the southern fill slope. Operator shall continue to monitor and manage this site until the location meets Rule 1003 standards, including weed management.