



**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

				corrective date
Type: Plunger Lift	# 3			
Comment:				
Corrective Action:		Date:		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 249070 Type: WELL API Number: 123-16872 Status: SI Insp. Status: SI**Idle Well**Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Corrective Action:  Date: \_\_\_\_\_**COGCC Comments**

Comment	User	Date
<p>On Thursday, June 13, 2019 at 09:40, I, Craig Carlile conducted an on-site inspection at: 329103 CRUICKSHANK 1C-24HZ            Operated by: Anadarko            While there I observed: Three wells on the location. This inspection is for API 05-123-16872, which is served by battery associated with location number,name: 328432, HSR-LONNY JOSEPH-63N66W 24NESE            Separate inspection for the other two wells on the location.            Weather: Skies clear, winds calm, temp 70 F            Possible compliance issues observed: None            This is a summary of the inspection report.</p>	carlilec	06/13/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690003678	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4849281">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4849281</a>