

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/13/2019

Submitted Date:

06/13/2019

Document Number:

690003697**FIELD INSPECTION FORM**

Loc ID 336245 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269204	WELL	SI	01/01/2019	OW	123-21641	CANNON 13-35	SI
297462	WELL	SI	01/01/2019	OW	123-27153	BROWN 33-35	SI
427889	WELL	SI	03/01/2019	OW	123-35156	BROWN 35N-26HZ	SI
427890	WELL	SI	03/01/2019	OW	123-35157	BROWN 13N-26HZ	SI
427893	WELL	SI	03/01/2019	OW	123-35160	BROWN 13C-26HZX	SI
427897	WELL	SI	03/01/2019	OW	123-35163	BROWN 14N-26HZ	SI

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Shared battery location number: 318146 Under reconstruction.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Inspected Facilities

Facility ID: 269204 Type: WELL API Number: 123-21641 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: si

Corrective Action: _____ Date: _____

Facility ID: 297462 Type: WELL API Number: 123-27153 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: si

Corrective Action: _____ Date: _____

Facility ID: 427889 Type: WELL API Number: 123-35156 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: si

Corrective Action: _____ Date: _____

Facility ID: 427890 Type: WELL API Number: 123-35157 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: si

Corrective Action: _____ Date: _____

Facility ID: 427893 Type: WELL API Number: 123-35160 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: si

Corrective Action: _____ Date: _____

Facility ID: 427897 Type: WELL API Number: 123-35163 Status: SI Insp. Status: SI

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: si

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
Routine inspection.	carlilec	06/13/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690003698	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4849290