

Interim Reclamation and Stormwater Inspection

June 12, 2019

Operator: EXTRACTION OIL & GAS INC #10459

Location ID: 450197

Inspection Document #: 697500199

Larimer County, CO

NESE Section 26 T5N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: McGirr /26-L
Location ID: 450197



Photo 1. Photo taken from the western interim reclamation area, facing South. Operator is in-process of performing interim reclamation activities. The previous corrective action for erosion on the fill slopes has been mitigated by reducing the steepness by extending the location outward.



Photo 2. Photo taken from the western interim reclamation area, facing North. See comments under Photo 1.

Inspection Photos
Location Name: McGirr /26-L
Location ID: 450197



Photo 3. Photo taken from the northwestern perimeter of location, facing South. Photo illustrates the Operator is performing construction activities (i.e., interim reclamation) and has failed to install perimeter BMPs.

Inspection Photos
Location Name: McGirr /26-L
Location ID: 450197



Photo 4. Photo taken from the northwestern perimeter of location, facing East. See comments under Photo 3.

Inspection Photos
Location Name: McGirr /26-L
Location ID: 450197



Photo 5. Photo taken from the northeastern perimeter of location, facing West. Photo illustrates the ditch and berm BMP that was previously installed during initial construction activities; however, the Operator has failed to install perimeter BMPs for other portions of the disturbance area.

Inspection Photos
Location Name: McGirr /26-L
Location ID: 450197



Photo 6. Photo taken from the northeastern perimeter of location, facing East. Photo illustrates soil material has covered up the previous ditch and berm (highlighted in red) and has failed to install perimeter BMPs.