

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/13/2019

Submitted Date:

06/13/2019

Document Number:

695100886**FIELD INSPECTION FORM**
 Loc ID 324493 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num:           
**Operator Information:**OGCC Operator Number: 66561Name of Operator: OXY USA INCAddress: PO BOX 27757 #110City: HOUSTON State: TX Zip: 77227-**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Giussani, Albert	806-894-0200/806-638-1296	albert_giussani@oxy.com	Engineering Advisor
Maestas, Eric	575-420-7825	eric_maestas@oxy.com	
Montgomery, Kelley		Kelley_Montgomery@oxy.com	
Labowskie, Steve		steve.labowskie@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
150117	UIC DISPOSAL	AC	04/05/1982		-	GARCIA 1 (EPA)	AC

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	PHOTO 8: HAZARD LEVEL NUMBERS ARE FAIDED AND NOT LEGABLE ON LARGER PRODUCED WATER TANK (SOUTHEAST TANK). ALSO CAPACITY OF TANK IS NOT POSTED. PHOTO 9: CAZARD LEVEL NUMBERS ARE FAIDED AND NOT LEGABLE ON LARGER PRODUCED WATER TANK (SOUTHEAST TANK). ALSO CAPACITY OF TANK IS NOT POSTED.		
Corrective Action:	COMPLY WITH 210 SERIES RULES. 7/13/19	Date:	07/13/2019
Type	WELLHEAD		
Comment:	PHOTO 1: WELLHEAD/ WELLSIGN/ CURRENCT OPERATOR IS NOT POSTED ON WELLSIGN 911 IS NOT POSTED AS EMERGENCY CONTACT.		
Corrective Action:	IF 911 SERVICES THIS AREA POST 911 AS EMERGENCY CONTACT ALSO POST CURRENT OPERATOR SIGN IN ACCORDANCE WITH 210 SERIES RULES.	Date:	07/13/2019

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	PHOTO 2: IMPACTED SOIL AROUND WELLHEAD.		
Corrective Action:	Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907.	Date:	07/13/2019
Type	OTHER		
Comment:	PHOTO 3: IMPACTED SOIL AROUND OIL TANK. PHOTO 4: IMPACTED SOIL IN CONTAINMENT SOUTHWEST OF PRODUCED WATER TANK. PHOTO 5: IMPACTED SOIL IN CONTAINMENT SOUTH OF OIL TANK. PHOTO 6: IMPACTED SOIL IN CONTAINMENT SOUTHWEST OF OIL TANK.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a.	Date:	07/13/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 1	
Comment:	IS PLUMBED TO SURFACE	
Corrective Action:		Date:
Type: Vertical Separator	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		FIBERGLASS AST		37.655710,-105.180420
Comment:	TANK CAPACITY IS NOT POSTED SEE SIGNS SECTION ON THIS PAGE FOR DETAILS.				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		FIBERGLASS AST		37.655710,-105.180420
Comment:	TANK CAPACITY IS NOT POSTED SEE SIGNS SECTION ON THIS PAGE FOR DETAILS.				
Corrective Action:					Date:

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

**Inspected Facilities**Facility ID: 150117 Type: UIC API Number: - Status: AC Insp. Status: AC**COGCC Comments**

Comment	User	Date
THIS IS A FOLLOWUP WELL TO INSP. DOC#682600339. IT APPEARS PREVIOUS CORRECTIVE ACTIONS HAVE BEEN ADDRESS HOWEVER THERE ARE NEW CORRECTIVE ACTIONS.	beardslt	06/13/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100887	LOCATION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4849777">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4849777</a>