

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/07/2019

Submitted Date:

06/07/2019

Document Number:

687904888**FIELD INSPECTION FORM**

Loc ID 313553 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10343Name of Operator: QEP ENERGY COMPANYAddress: 1050 17TH STREET - SUITE 800City: DENVER State: CO Zip: 80265**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Jacobson, Julie		julie.jacobson@qepres.com	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224459	WELL	PR	01/01/2011	OW	083-06524	CUTTHROAT 8	PR

General Comment:[Site inspection with photos at the end of this report.](#)

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank and non-potable water tank labels do not reflect current operator. See photo # 5,14		
Corrective Action:	Update labels to reflect current operator per Rule 210.d.	Date:	07/07/2019
Type	WELLHEAD		
Comment:	Seeley Oil Company sign posted at entrance to location.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Seeley Oil Company contact information posted on sign.		
Corrective Action:		Date:	

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds around fired equipment. See photo #6		
Corrective Action:	Control weeds per Rule 603.f.	Date:	06/17/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:	Bird protectors are inadequate and have holes in them. See photo #3,16		
Corrective Action:	Repair wildlife protection devices per Rule 324A.a.	Date:	06/17/2019
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		

Comment:	Stained soil around wellhead. See photo #7		Date:	
Corrective Action:	Clean-up and dispose of soil per Rule 906.a. and Rule 1002.f(2)		Date:	07/07/2019
Type: Flow Line	# 10			
Comment:	2-2" flowlines from wellhead to separator. 1-1" flowline from wellhead to pump jack engine fuel gas. 2-1" flowlines from separator to heated tank fuel gas. 2-2" flowlines from separator to produced water tank. 1-2" flowline from separator to meter house. 1-2" flowline from meter house to natural gas gathering system. 1-2" flowline from separator to offsite oil gathering system.			
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	STEEL AST		
Comment:	Tank labels need to be updated to current operator. See CA under labeling.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Berm maintenance is inadequate. Berm has eroded and has wildlife burrows along walls.			
Corrective Action:	Repair berms per Rule 906.d.(1)			Date: 07/07/2019

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	224459	Type:	WELL	API Number:	083-06524	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing.								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Ditches	Pass			
				Material Handling And Spill Prevention	Pass	Spill prevention for chemical injection.
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402068486	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4844019
687904889	Cutthroat unit 8 inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4844014