

Gordon Engineering
API # 05-077-08516
Inspection # 696600130



Photo #1 Photo from entrance of location.

Gordon Engineering
API # 05-077-08516
Inspection # 696600130



Photo #2 Well heads and signs on location.



Photo #3 Photo taken of tank battery and sign

Gordon Engineering
API # 05-077-08516
Inspection # 696600130



Photo #4 Riser not Locked Out / Tagged Out



Photo #5 Riser not Locked Out / Tagged Out

Gordon Engineering
API # 05-077-08516
Inspection # 696600130



Photo # 6 unused riser left stored on location. Orange Riser not LOTO

Gordon Engineering
API # 05-077-08516
Inspection # 696600130



Photo #7 Berm around outside of metal berm needs maintenance if going to use as secondary containment.



Photo #8 Hole in tank liner.