

Inspection Photos  
Location: Fish Creek 2  
Inspection Date: 6/13/2019  
Photos taken by Kris Neidel



Pumpjack is in back of photo. Water seen in road is coming from hillside to the north of the well. It is known that there are springs and water coming out of the hill



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Location: Fish Creek 2  
Inspection Date: 6/13/2019  
Photos taken by Kris Neidel



Tank battery on left

Inspection Photos  
Location: Fish Creek 2  
Inspection Date: 6/13/2019  
Photos taken by Kris Neidel



Well, some staining from exhaust on pumpjack



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Location: Fish Creek 2  
Inspection Date: 6/13/2019  
Photos taken by Kris Neidel



Pipe riser that had failed

Inspection Photos  
Location: Fish Creek 2  
Inspection Date: 6/13/2019  
Photos taken by Kris Neidel



Area inside tank battery



Inspection Photos  
Location: Fish Creek 2  
Inspection Date: 6/13/2019  
Photos taken by Kris Neidel



Pooled water just outside of tank battery. Appears to be from hillside



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Location: Fish Creek 2  
Inspection Date: 6/13/2019  
Photos taken by Kris Neidel



Looking up hill, mostly north

Inspection Photos  
Location: Fish Creek 2  
Inspection Date: 6/13/2019  
Photos taken by Kris Neidel



Wellhead, historic staining.



Inspection Photos  
Location: Fish Creek 2  
Inspection Date: 6/13/2019  
Photos taken by Kris Neidel

